## DESCRIPTION OF ACCIDENT

(Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

Examination of the wreckage indicated that the left wing became separated from the aircraft while in flight. The left wing with number one engine was found appreximately one-half mile from the remainder of the aircraft. The wing was broken off at a point between number one and number two engine at station number ten. The break extended from the leading to trailing edge of the wing through reinforcement plates on the lower surface of the wing where sometime previous flak damage had occurred.

Detailed inspection of section of wing which broke loose showed the skin was forced outward. This, along with the indication of a small electrical fire in number two engine necelle, and with the clean shearing of the rivets on the patch would seem to indicate the possibility of an internal explosion with an immediate break occurring rather than a gradual weakening of the wing.

Subject airplane was repaired by the 60th Service Squadren for flak damage received on 21 July 1944. Subject airplane had participated on twenty-six sembat missions with a total of 288:50 hours since wing was repaired.

In the epinion of the accident beard it is impossible to determine the exact cause of the accident since the airplane was completely destroyed.

## RESPONSIBILITY

100% Material Failure

JAMES B. HAPPA Colempl. Air Corps.

Major, Air Corps.

William H. Maddler,
William H. Mohanus, JR.

William H. Mohanus, JR.

William H. Homanus, JR.

William H. Homanus,

Signature (Investigating Officer)

Date

## MEDICAL OFFICER'S REPORT CO AIRCRAFT ACCIDENT

Station Investigating Accident - 451st Bombardment Group (H) \*

Place of Accident - 4 mi E Ordona, Italy - Plane Ty - B-24H

Mission - Training - Date Accident - 14 November 1944 - Time Accident - 1224A

Manner of Occurrence and Probable Gause of Accident - Examination of the wreckage indicated that the left wing became separated from the amoraft while in flight.

The left wing with number one engine was found approximately one-hale mile from the remainder of the aircraft. The wing was broken off at a point between number one and number two engine at station number ten. The break extended from the leading to trailing edge of the wing through reinforcement plates on the lower surface of the wing where sometime previous falk damage had occurred.

Detailed inspection of section of wing which broke bose showed the skin was forced outward. This, along with the indication of a small electrical fire in number two engine nocelle, and with the clean shearing of the rivets on the patch would seem to indicate the possibility of an internal explosion with an immediate break occurring rather than a gradual weakening of the wing.

Subject airplane was repaired by the 60th Service Squadron for flak damage received on 23 July 1944. Subject airplane had participated on twenty-six combat missions with a total of 288:50 hours since wing was repaired.

In the opinion of the agcident board it is impossible to determine the exact cause of the accident since the airplane was completely destroyed.

Pilot Name - Sellers, William N. - ASN 0-813073 - Age - 27 - Rating - Pilot

Total Pilot Hours - 949:20 - No. Pregious Accidents - None - Date Last Physical Emm. - 21/Aug/44 - History of Physical or Heuropsychic Dedects - None

Copilot Name - Haynes, Alfred A. - ASNO777667 - Age - 27 - Rating - Copilot

Total Pilot Boars - 444:55 \* No. Previous Accidents - None - Date Last Physical Exam. - 21/Aug/44 - Mistory of Physical or Neuropsychic Defects - None

No. Persons in Place - 11 - No. Persons killed - 11 - No. Persons Injured - 0

Injuries to Personnel:

Sellers, Willia 2nd Lt. 0-813073 B -Haynes, Alfred A. 2nd Lt. 0-777667 CP @ Huck, David W. Jr. 2nd Lt. 0-2063432 N Anderson Harry F. 2nd Lt. @0-780139 B Myrick, Lawrence W. Sgt. €34463355 E Davis, William H. 31341167 RO Sgt.

www. Allen r. ng u. 12101063 Swain Fichard W. S to Set. \* 13044595 AD Colvard, Eugene J. 31379131 Dennehy, Robert W. Sgt. A.G AC 34339295 S/Stt. Cross, Clinton B.

All con but empeted fractures of the head and back. Many had amputation of arms and legs. All remains were severely burned.

EQUIPMEN CARCS:

Date - 28 November 1944

Sents is post order? Yes - Seat belts provided? - Yes - How many? 2

Is good exter? - Tes - Shoulder harness provided? - Yes - How many? - 2

yes

In good order? - Yes - Parachutes provided?/- How many? - 11 - In good

order? - Yes - Oxygen equipment provided? - Yes - Type - Demand & In

goed order? - Yes - Special safety devices? • None - Material factors

which contributed to or prevented injury? - Left wing torn loose between

#1 and #2 engine. A/C crashed and burned resulting in complete destruction.

General Statement regarding accident with recommendations - None

CLYVE L. WAGNER
Major, Medical Corps
Group Flight Surgeon

WAR DEPARTMENT WAR DEPARTMENT UE AAF Form No. 54 (Reviod 2 18-43) ARMY AIR FORCES TO BE FILLED IN BY STATION LEAVE BLANK A.S.C. Serial No. Clar Station Serial No. Date Submitted 44-479 11-22-44  $U_{\mathsf{R}}$ (See AAfrica. 15-54 for information on Proper use at this form) ORGANIZATION STATION 451st Bomb Gp (H) 725th Bomb Sq (H) APO 520 Manufacturer AAR Order or Shipping So. SUBJECT Property Class Name OF REPORT Douglas W-535-AC-18723 Wing Center Section AIRCRAFT - Model & AAF Serial No. ENGINE - Model & AAF Serial No. UNIT OR ACCESSORY - Type, Model and Serial No. B-24H 42-51090 Total Flying Time LAST D.I.R. - Depot Date Flying Time Stoce AIRCRAFT REPORTS ONLY Depots and Hours At Each Previous Overhaul UR ENGINE REPORTS ONLY LAST OVERHAUL - Depot. Hours Since Part Drawing, Serial and Specification No. 32W2002-4 Wing Center Section laspectar's No. or identification No. Previous Tailures Manufacturer Time in Use Ouastity on Mand Quantity Known Defective Douglas Mone 689:15 12 Photographed and Prints Enclosed Repaired and Returned to To Overhau Indicate by «X»
Disposition
of Exhibit Sent in Attached Sent Under Disposed of (Explain Separate Facility (INITIALS.) Service GIVE COMPLETE DETAILS, PROBABLE CAUSES AND RECOMMENDATIONS BELOW: EXPEDITE (Use Unly Applicable Spaces Above - Avoid Unnecessary Repetition)  $\mathsf{U}_\mathsf{R}$ MATERIAL FAILURE 1. DESCRIPTION OF TROUBLE: Twenty (20) minutes after take off B-24H Airplane, AAF No. 42-51090 crashed. Investigation revealed that Wing Center Section, Part No. 32W2002-4, broken at left wheel well, station 10. Further investigation revealed UR that break occured at a repair on reinforcing plates at lower surface of wing near wheal well as shown in exhibits. Subject airplane was repaired by 60th Service Squadron for flak damage received, July 21, 1944. Airplane time, 400:25, at time of damage. Subject airplane has flown twenty-six (26) combat missions with a total of 288:50 hours since wing was repaired. HISTORICAL DATA: Airplane accepted by this Squadron, May 11, 1944. ACTION TAKEN TO CORRECT: None. UR Complete destruction by crash and fire. DISPOSITION: Mone. @ PREVIOUS REPORTS:  $u_R$ RECOMMENDATIONS: 7. GENERAL REMARKS: This Unsatisfactory Report is submitted in accordance with the provisions of AAF Regulation 62-14A, dated May 28, 1943. CORPORE SOL PHOTOGRAPHS: \*Attached. UR  $\mathsf{U}_\mathsf{R}$ " W. I amak J.W. RAMSEY. Capt., AC, Engineering Officer. UR RESTRICTED SEND ORIGINAL AND TWO COPIES DIRECT TO COMMANDING GENERAL ROUTING HQ: AIR SERVICE COMMAND, PATTERSON FIELD, FAIRFIELD, OHIO. P.S.S. B, M238b . 500×100 . 7 -44