Authority: NND 735001 By: NARA NARA Date: 1973

. A.	STRICTED 40
	BRAEUMAS, Lt. Col., AC WAR DEPARTMENT MUENCH, Capt., AC HEADQUARTERS ARTY AIR TYPEDS 7211 - 800;
	IMPORTANT: This report will be compiled by eachmy Air Forces organization within 48 hours of the time personnel are officially reported missing.
1.	ORGANIZATION: Location Castelluccic, Italy Command or AF 15th A. F. Group 451st Homberdmont Group (H.) Squadron 726th Bomberdm
2.	Smedr
3.	WEATHER CONDITIONS AND VISIBILITY AT TIME OF CRASH OR WHEN LAST REPORTED:
4.	GIVE: (a) Date 26 July 1944 Tian 0806 Location 16 miles off coast
	of last known whereabouts of alssing Albania. (b) Specify whether: (c) Last Times (c) Last Contacted by Radio (c) Forced Down (c) See to Crash; or (c) Information not available.
5.	AIRCRAFT M.S LOST, OR IS BELIEVED TO HAVE BEEN LOST, AS A RESULT OF: (Check only one) () Enemy Aircraft () Enemy Anti-Aircraft (X) ——————————————————————————————————
6.	AIRCRAFT: Type, Model & Series U.F Serial No.
.7.	ENGINES: Type, Model & SeriesF Serial No. (a) (b) (c) /d)
8.	(a) (b)
	(c) (d) (e) (f) (h)
9.	PERSONNEL LISTED BELOW REPORTED AS: () Battle Casualty () Won-Battle Cas.
10.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on sociarate sheet and attach to this form)
j	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on separate sheet and attach to this form) "A E IN FULL DATE OF KIN, RELATIONSHIP CREW POSITION (Last name first) RANK SERIAL MO AND ADDRESS "Ended Bombardie-Fook, Roland E. 2nd It (0-706702 Mr. Ripley E. Gook (Father
1.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on separate sheet and attach to this form) TAE DU FULL CREW POSITION (Last name first) RAM STRILL NO AND ADDRESS MAD THE FULL NEXT OF KIN, RELATIONSHIP CREW POSITION (Last name first) RAM STRILL NO AND ADDRESS MAD THE FULL STRILL NO AND ADDRESS MAD TO THE MOLEGIAN FAMOR J. STRILL NO CONTROL OF THE MOLEGIAN MOSE Gummer 7 Molegian James J. Sgt S2848524 Mrs. Clerym Molegian (Mother
1. :	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on separate sheet and attach to this form) "A D DU FULL CREW POSITION (Last name first) RAWK SERIL MO AND ADDRESS MAGOT Bombardies Gook, Roland E. 2nd 1t (0-706702 Mr. Ribley E. Gook (Father A 944 W Wood St., Drummicht, Oklas
1. : 2. 3. 4.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on sociarate sheet and attach to this form) "A ID IN FULL CREW POSITION (Last name first) R.M. SERLL MO AND ADDRESS "Matter Bomberdie-Flook, Roland B. 2nd Lt 0-706702 Mr. Ripley E. Gook (Father Mose Gumer 9 Molean, James J. Set 32848524 Mrs. Clr Me Molean (Mother 101 Matter Sh., Binghanton, N. Y. Pilot Beaucond, Maurice J. Jr. 2nd Lt. 0-709893 Present for duty Go-pilot Jeffress, Weldon H. 2nd Lt. 0-709885 Present for duty
1. 2. 3. 4. 5.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on separate sheet and attach to this form) "A E IN FULL NO AND ADDRESS That Bomberdie-Jook, Roland E. 2nd It (0-706702 Mr. Ripley E. Gook (Father Ness Gummer & Molean, James J. Set S2848524 Mrs. Clr vs Molean (Mother Pilot Deaucond, Maurice J., Jr. 2nd It. 0-700893 Present for duty Newigator Grapey, Sidney S. 2nd It. 0-719850 Present for duty Top Turret
1. : 2. 3. 4. 5. 6.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on sociarate sheet and attach to this form) "A D DI FULL CREW POSITION (Last name first) R.MK STRILL MO AND ADDRESS "Milot Bomberdie-Gook, Roland B. 2nd 1t 0-706702 Mr. Ripley E. Gook (Father 10 Wester Strick) Mose Gummer Molean, James J. Set S2848524 Mrs. 01 Maldan (Mother 10 Wester Str. Binghanton, N. Y. Pilot Beaucond, Maurice J. Jr. 2nd 1t. 0-709585 Present for duty Newigator Grapey, Sidney S. 2nd 1t. 0-719850 Present for duty Top Turret Gunaer Gibson, William T. Sgt. 34650016 Present for duty
1. 2. 3. 4. 5. 6. 7.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on separate sheet and attach to this form) A D IN FULL CREW POSITION (Last name first) R.MK STRILL NO AND ADDRESS Didot Bomberdie-Jook, Roland E. 2nd It (0-706702 Mr. Ripley E. Gook Father Nose Gunner & Molean, James J. Set. 32848524 Mrs. Clr Ne Molean (Mother 101 Mater Sh. Binghauten, M. Y. Pilot Deaucond, Maurice J. 17. 2nd It. 0-709893 Present for duty Newigator Grapey, Sidney S. 2nd It. 0-709856 Present for duty Newigator Grapey, Sidney S. 2nd It. 0-719850 Present for duty Top Turret Gunner & Gibson, William T. Sgt. 34650016 Present for duty Lower Turret Gunner Wartin, Oliver H. Sgt. 38512700 Present for duty
1. ; 2. 3. 4. 5. 6. 7. 3.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on sociarate sheet and attach to this form) ALC IN FULL CREW POSITION (Last name first) RAM STRILL NO AND ADDRESS Midot Bombardie-Jook, Roland E. 2nd It (0-706702 Mr. Ripley E. Gook (Father 101 Water St., Druwwight, Okla. Ness Gunner / Nolean, James J. Set. 32348524 Mrs. Cl. na Molean (Mother 101 Water St., Binghanton, N. v. Pilot / Beaucond, Maurice J. Jr. 2nd It. 0-709893 Present for duty Navigator Grapey, Sidney S. 2nd It. 0-709885 Present for duty Navigator Grapey, Sidney S. 2nd It. 0-719850 Present for duty Top Turret Gibson, William T. Sgt. 34650016 Present for duty Tail Bolin, Billy R. Sgt. 38512700 Present for duty
1. 2. 3. 4. 5. 6. 7. 3. 9.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on sociarate sheet and attach to this form) "ALL DI FULL NO STRILL NO AND ADDRESS "Milot Bomberdie-Gook, Roland B. 2nd Lt 0-706702 Mr. Ripley E. Gook (Father Nose Gumer 9 Molean, James J. Set 32848524 Mrs. Clr vm Molean (Mother 101 Matter Sh., Blinghardton, M. v. Pilot Beaucond, Maurice J. Jr. 2nd Lt. 0-709893 Present for duty Go-pilot Jeffress, Weldon H. 2nd Lt. 0-709895 Present for duty Navigator Grapey, Sidney S. 2nd Lt. 0-709896 Present for duty Navigator Gibson, William T. Sgt. 34650016 Present for duty Lower Turret Gumer Gibson, William T. Sgt. 38512700 Present for duty Tail Bolin, Billy R. Sgt. 38512700 Present for duty Waist D Smith, Willard E. S/Sgt./ 37657815 Present for duty
1. ; 2. 3. 4. 5. 6. 7. 3.	(Starting with "Pilot" furnish the following particulars; if more that 12 persons were aboard list similar particulars on sociarate sheet and attach to this form) "A D DI FULL CREW POSITION (Last name first) R.MK STRILL MO AND ADDRESS. That the first of the condition of the c

Authority: NND 735001 By: NARA NARA Date: 1973

NEW YORK		•	American Miles In .		
	CONFID	NILAL	1141 (841-4)7		
11.	INDENTIFY BELOW THOSE PERSONS WHO AIRCRAFT AND CHECK APPROPRIATE (
	NAME IN FULL RANK SERIAL	Contacted NO by Radio	Inst Saw Sighted Crash Forced Land		
	Beaucond, Maurice J. 2nd Lt. 0-	70 893	x		
3.					
4.					
6.					
12.	IF PERSONNEL ARE BELIEVED TO HAVE SURVIVED, CHECK ONE OF THE FOLLOWING: (C) Parachutes were used (,) Persons seen walking away, from scene of crash () Any other reason (specify)				
13.	ATTACH, AS AT INCLOSURE TO THIS REPORT, EITHER LERIAL PHOTOGRAPH, MAP, CHAPMOR SKETCH, SHOWING APPROXIMATE LOCATION THERE LIRCRAL TAS LAST SEEM.				
14.	ATTACH, AS DICLOSURES TO THIS REPORT, EYEMITMESS DESCRIPTIONS OF CRASH, FORCED LANDING, OR OTHER CIRCUMSTATCES PERTAINING TO MISSING AIRCRAFT.				
15.	ATTACH, AS AM INCLOSURE TO THIS RESEARCH, IF AMY, AND GIVE NAME, RANHERE: (if no search, so state give	K. JO SERIAL M	UMBER OF OFFICER IN CHARGE		
	members bailed out over enemy ter		3 SOAL OIL WAS LEXUED AS 010W		
		Data	of this report 28 July 19		
			11 400		
			1019		
2	Incls: Incl 1 - Statement (S-2 Officer)		ture of Preparing Officer		
	Incl 2 - Statement (Pilot)		SERT F. OGG, ptain, Air Corps,		
	Incl 3 - Sketch.		jutant.		
	- A				
			-		

MECEINED

ALC: 0 & 9UA

Authority: NND 735001 By: NARA NARA Date: 1973



726TH BOMBARDMENT SQUADRON (H)
451ST BOMBARDMENT GROUP (H)
APO 520 U.S. ARMY

28 July 1944

STATEMENT

2nd Lt. Roland E. Cook, 0-706702, bombardier and Sgt. James J. McLean, 32848524, nose gunner, were on a bombing mission over Berat, Albania in a B-24 type aircraft piloted by 2nd Lt. Maurice J. Beaucond, 0-700893 on 26 July 1944.

The aircraft was proceeding on course with the formation and had almost reached the Albanian coast when a fire broke out in the number of engine. The airplane turned back and left the formation. The pilot pressed the emergency button for all members of the crew to put on their parachutes. Apparently mistaking this for the signal to jump, Lt. Cook and Sgt. McClean left the aircraft by way of the nose bay doors. The ships location at that time was approximately 16 miles off the coast of Albania, 410 0" North & 190 20" East. They were last seen going down with open chutes, with the wind blowing them in the direction of land. The aircraft returned safely to an alternate airfield. The undersigned has no opinion as to the final fate of the two crew members.

ALBERT L. ROEMER, 1st Lt., Air Corps, S-2 Officer.

gue # 1"

CONFIDENTIAL



Authority: NND 735001 By: NARA NARA Date: 1973



7261. BOMBANDMENT SQUADRON (H)
451ST BOMBANDMENT GROUP (H)
APO 520 U. S. ARMY

28 July 1944.

STATEMENT

I, 2nd Lt. Maurice J. Beaucond, 0-700893 was pilet of the B-24 type aircraft from which 2nd Lt. Roland E. Cook, 0-706702, tembardier, and Sgt. James J. McLean, 32848524, nose gunner, bailed out over the Albanian coast on 26 July 1944.

We were proceeding on course with the formation and had almost reached the Albanian coast when number 4 engine caught fire and the proposame off at the same time. Number 1 engine dropped to less than its power and later quit altogether. I pressed the emergency button for all members of the crew to put on their parachutes. Apparently alarmed by the fire, Lt. Cook and Sgt. McLean, must have mistaken the signal for notice to jump. I am not certain whether they jumped before or after I gave the alarm, but they did leave the plane by way of the nose bay doors. The plane's location at that time was 41°0" North & 190 20" East, approximately 3 miles off the coast of Albania. Their parachutes were seen to open and they were being blown in the direction of land. The fire having been extinguished, I flew my ship to an alternate airfield and landed safely with the rest of the crew.

MAURICE J. BEAUCOND, 2nd Lt., Air Corps, Pilot.

Maurice Beaucard for dul 47

Inol. # 2'

CONFIDENTIAL